

EPA APPROVED  
THIS PROCESS IS EFFECTIVE AGAINST:

Test Organism	ID	Kill Time
Salmonella entrica	ATCC 10708	5 min
Staphylococcus aureus	ATCC 6538	5 min
Staphylococcus aureus-MRSA	ATCC 33592	5 min
Staphylococcus aureus & Enterobacter aerogenes	ATCC 13048	5 min
<b>Bacteria</b>		
Pseudomonas aeruginosa	ATCC 15442	10 min
Staphylococcus aureus	ATCC 6538	10 min
Salmonella enterica	ATCC 10708	10 min
Staphylococcus aureus-MRSA	ATCC 33592	10 min
Enterobacter aerogenes	ATCC 13048	10 min
Escherichia coli	ATCC 11229	10 min
Sulfate Reducing Bacteria		
<b>Viruses</b>		
Human Immunodeficiency Virus type 1 (HIV-1)	Strain HTLV IIIB	10 min
Influenza A virus Hong Kong (flu virus)	ATCC VR-544	10 min
Avian Influenza A (H5N1) virus (flu virus)	Strain VNH5N1	10 min
Rhinovirus type 37	ATCC VR-1147	10 min
Swine Influenza A (H1N1)	ATCC VR-333	10 min
<b>Fungi</b>		
Allergenic		10 min
Mycotoxic		10 min
Pathogenic		10 min

# CLEAN SLATE

Pro Active Home Safety Service  
410-310-1558

Laboratory Standard Air Disinfection  
Like dipping your home into a bottle of Hydrogen Peroxide X2



## If you need clean air

12 Step Affordable Program of Cutting Edge Technology and Prudent  
Established Work Practices featuring Pat Pending Fairhaven H.P. System

Hydrogen Peroxide H2O2 Active Disinfectant turns to H2O (water)  
Commercial HEPA Negative Air Scrubbers - 00.07%

**Gary Fairbank**

410-310-1558 • [Fairbanksenviro@aol.com](mailto:Fairbanksenviro@aol.com)  
Office - 410-310-2631

OSHA - Hazardous Waste Operations and Emergency Response  
M.D. Mol Supervisor • Md. Asbestos • American Indoor Air quality Association  
Chesapeake Technology Council

Licensed and Insured

Electrically charged ionic silver and H2O2 disinfection systems have been used for 30 years in parts of Europe. Where the MRSA and C-Dif infection rates are 100 times lower than the USA at .4 compared to 4% to 5% in the US.

## **HOME SAFE PROGRAM**

- 1) Establish Fairhaven Negative Air H.P. System evacuate dirty air 10 times then adjust to Scrub.
- 2) Under Negative air remove and clean HVAC - grated and vents. Coated with EPA approved fungicidal encapsulant.
- 3) Clean flex duct lines with contact system under negative pressure - HEPA evacuation. Supply and Return.
- 4) Encapsulate flex ducts with EPA approved fungicidal encapsulant to prevent future intrusions.
- 5) Dryer vent hose - cleaned - disinfected - checked for leaks.
- 6) Bathroom fans - cleaned - disinfected - check and clean stove/oven fan if possible.
- 7) Replace and or clean HVAC filter.
- 8) Window sills thoroughly cleaned HEPA vacuumed - loose paint and dirt removed sealed with paint or mold encapsulant.
- 9) Walls, floors and ceilings wiped down to no visible residue using owner approved commercial products.
- 10) Moisture Tests - 10 samples - detailed map of results.
- 11) Entire home HEPA vacuumed with commercial grade TRUE HEPA 99% efficiently.
- 12) Whole home disinfection with Fairhaven H.P. Pat. Pending System - dispersal droplet size .15 microns for dry fog.

Because all houses are in different conditions, prices will be higher for extremely degraded residences. You will be informed before any work is done; this rarely happens.

## **Additional Services**

Mold Abatement

Asbestos Abatement

Mold Air Testing - Type and Count Analysis N.I.S.T.  
Approved Laboratory

Demolition - Done correctly under HEPA negative air containment so no cross containment - critical barriers for separation

HVAC Truck Lines/Air Handlers

Dehumidification - Dry Out

Please call  
**GARY FAIRBANK**  
Cell 410-310-1558  
Office 410-310-2631